10/726,675.



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of : Attn: Certificate of

Correction Branch

Koichi HIRANO et al.

Patent No. 7,126,811 : Atty Docket No. 2003 1690A

Issued October 24, 2006 : Confirmation No. 5709

CAPACITOR AND METHOD FOR PRODUCING THE SAME, AND CIRCUIT BOARD WITH A BUILT-IN CAPACITOR AND METHOD FOR PRODUCING THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

In accordance with the provisions of 37 CFR 1.322, it is respectfully requested that a Certificate of Correction issue to correct the following:

Column 38,

Line 64, "through holes" should read --through hole--.

Certificate

DEC 0 6 2006

of Correction

THE COMMISSIONER IS AUTHORIZED TO CHARGE ANY DEFICIENCY IN THE FEES FOR THIS PAPER TO DEPOSIT ACCOUNT NO. 23-0975

REMARKS

The above-noted error in the claims apparently arose due to a PTO mistake. In particular, it is noted that the requested correction can be found in the Amendment filed on June 7, 2005. Accordingly, a Certificate of Correction should issue at no expense to patentee. Form PTO-1050 accompanies this request.

Respectfully submitted,

Koichi HIRANO et al.

y <u>uunth</u>

Registration No. 52,430

Attorney for Patentees

KWF/jmj Washington, D.C. Telephone (202) 721-8200 Facsimile (202) 721-8250 December 4, 2006 To: The Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

7,126,811

DATED

October 24, 2006

INVENTOR(S)

Koichi HIRANO et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 38,

Line 64, "through holes" should read --through hole--.